

**Exide Frankfort IN  
555 North Hoke Avenue, Indiana**

As a follow-up to the Technical Memo regarding site water runoff, a local paving contractor was contracted to seal the cracks and install a rolled asphalt curb in the infiltration gallery area to mitigate future potential run off from this area. The photos were taken August 13, 2025.



Photograph 1 – New 6-inch curb installed adjacent to east side of infiltration gallery





**Exide Frankfort IN  
555 North Hoke Avenue, Indiana**

As a follow-up to the Technical Memo regarding site water runoff, a local paving contractor was contracted to seal the cracks and install a rolled asphalt curb in the infiltration gallery area to mitigate future potential run off from this area. The photos were taken August 13, 2025.

Photograph 2 – Southern end of curb – note crack sealing



Photograph 3 – Northern end of 6-inch curb



**Exide Frankfort IN  
555 North Hoke Avenue, Indiana**

As a follow-up to the Technical Memo regarding site water runoff, a local paving contractor was contracted to seal the cracks and install a rolled asphalt curb in the infiltration gallery area to mitigate future potential run off from this area. The photos were taken August 13, 2025.

Photograph 4 – Crack sealing



Photograph 5 – Infiltration gallery injection point with bentonite seal.